

City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 1 of 1

Sewershed: Gwynns Falls

Company: Savin

Date: 9/8/2009

Test to be performed:

Smoke ☐ Dyed Water ☒

Ground Condition:

Dry ☒ Damp ☐ Wet ☐

Supervisor: JAW


Manhole_ID: S02EE1005MH

Test ID: D1032-027006

Notification Made: NA

(Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S02EE1005MH
0			Water Level	
124.5			Dye Test Visible	DYE SEEN AT JOINT
127.8000031			Dye Test Visible	DYE SEEN AT JOINT
130.8000031			Dye Test Visible	DTE SEEN AT JOINT
134			Dye Test Visible	DYE SEEN AT JOINT
158			Abandoned Survey	DYE TEST COMPLETE